

CLARKDIETRICH BUILDING SYSTEMS, LLC ACOUSTICAL PERFORMANCE TEST REPORT

SCOPE OF WORK ASTM E90 SOUND TRANSMISSION LOSS TESTING ON A UL-U465, WALL SYSTEM

REPORT NUMBER L3173.05-113-11-R0


TEST DATE 10/13/20

ISSUE DATE 01/05/21

PAGES

11

DOCUMENT CONTROL NUMBER RT-R-AMER-Test-2758 (01/24/19) © 2017 INTERTEK





130 Derry Court York, Pennsylvania 17406

Telephone: 717-764-7700 Facsimile: 717-764-4129 www.intertek.com/building

TEST REPORT FOR CLARKDIETRICH BUILDING SYSTEMS, LLC

Report No.: L3173.05-113-11-R0 Date: 01/05/21

REPORT ISSUED TO

CLARKDIETRICH BUILDING SYSTEMS, LLC 9050 Centre Pointe Drive West Chester, Ohio 45069

SECTION 1

SCOPE

Intertek Building & Construction (B&C) was contracted by ClarkDietrich Building Systems, LLC to conduct a sound transmission loss test. Results obtained are tested values and were secured by using the designated test methods. The complete test data is included herein. The client provided the test specimen. All measurements were conducted in the HT test chambers at Intertek B&C located in York, Pennsylvania.

This report does not constitute certification of this product nor an opinion or endorsement by this laboratory. Intertek B&C will service this report for the entire test record retention period. The test record retention period ends four years after the test date. Test records, such as detailed drawings, datasheets, representative samples of test specimens, or other pertinent project documentation, will be retained for the entire test record retention period.

For INTERTEK B&C: Zachary P. Golden Kurt A. Golden **COMPLETED BY: REVIEWED BY: Technician Team Leader** Project Lead TITLE: Acoustical Testing TITLE: **Acoustical Testing SIGNATURE: SIGNATURE:** 01/05/21 01/05/21 DATE: DATE: ZPG:jmcs

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample(s) tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.





TEST REPORT FOR CLARKDIETRICH BUILDING SYSTEMS, LLC

Report No.: L3173.05-113-11-R0 Date: 01/05/21

SECTION 2

SUMMARY OF TEST RESULTS

SERIES/MODEL	UL-U465
ТҮРЕ	Wall System
DATA FILE NO.	L3173.01C3
INSULATION TYPE	R-13 Fiberglass Unfaced
STC	53
OITC	37

SECTION 3

TEST METHODS

The specimens were evaluated in accordance with the following:

ASTM E90-09 (2016), Standard Test Method for Laboratory Measurement of Airborne Sound Transmission Loss of Building Partitions and Elements

ASTM E413-16, Classification for Rating Sound Insulation

ASTM E1332-16, Standard Classification for Rating Outdoor-Indoor Sound Attenuation

ASTM E2235-04 (2020), Standard Test Method for Determination of Decay Rates for Use in Sound Insulation Test Methods

SECTION 4

SPECIMEN INSTALLATION

The specimen was constructed in the laboratory. A sound transmission loss test was initially performed on a filler wall. The 96" wide by 96" high specimen plug was removed from the filler wall assembly. The specimen was placed on an isolation pad in the test opening. Duct seal was used to seal the perimeter of the specimen to the test opening on both sides. The interior side of the specimen, when installed, was approximately 1/4" from being flush with the receive room side of the filler wall. A stethoscope was used to check for any abnormal air leaks around the test specimen prior to testing.



TEST REPORT FOR CLARKDIETRICH BUILDING SYSTEMS, LLC

Report No.: L3173.05-113-11-R0 Date: 01/05/21

SECTION 5

EQUIPMENT

The equipment listed below meets the requirements of the test methods stated in Section 3 of this report.

INSTRUMENT	MANUFACTURER	MODEL	DESCRIPTION	ASSET #	CAL
					DATE
Data Acquisition Card	National Instruments	PXI-4462	Data Acquisition Card	63763-3*	04/20
Data Acquisition Card	National Instruments	PXI-4462	Data Acquisition Card	65125*	05/20
Data Acquisition Card	National Instruments	PXI-4462	Data Acquisition Card	65126*	05/20
Source Room Microphone	PCB Piezotronics	378C20	Microphone and Preamplifier	65968	01/20
Source Room Microphone	PCB Piezotronics	378B20	Microphone and Preamplifier	64903	09/20
Source Room Microphone	PCB Piezotronics	378B20	Microphone and Preamplifier	65103	03/20
Source Room Microphone	PCB Piezotronics	378B20	Microphone and Preamplifier	64905	03/20
Source Room Microphone	PCB piezotronics	378B20	Microphone and Preamplifier	64906	03/20
Receive Room Microphone	PBC Piezotronics	378B20	Microphone and Preamplifier	64907	01/20
Receive Room Microphone	PCB Piezotronics	378C20	Microphone and Preamplifier	64908	01/20
Receive Room Microphone	PCB Piezotronics	378B20	Microphone and Preamplifier	64909	01/20
Receive Room Microphone	PCB Piezotronics	378B20	Microphone and Preamplifier	64910	01/20
Receive Room Microphone	PCB Piezotronics	378B20	Microphone and Preamplifier	65586	08/20
Receive Room Environmental Indicator	Comet	T7510	Receive Room	64915	01/20
Source Room Environmental Indicator	Comet	T7510	Source Room	64914	02/20
Microphone Calibrator	Norsonic	1251	Acoustical Calibrator	Y002919	04/20

*- Note: The calibration frequency for this equipment is every two years per the manufacturer's recommendation.

TEST CHAMBER

	VOLUME	DESCRIPTION
RECEIVE ROOM	234 m³	Rotating vane and stationary diffusers
		Temperature and humidity controlled
		Isolation pads under the floor
SOURCE ROOM	207 m ³	Stationary diffusers only
		Temperature and humidity controlled

	MAXIMUM SIZE	DESCRIPTION
TL TEST OPENING	4.27 m wide by 3.05 m high	Vibration break between source and receive rooms



TEST REPORT FOR CLARKDIETRICH BUILDING SYSTEMS, LLC

Report No.: L3173.05-113-11-R0 Date: 01/05/21

SECTION 6

LIST OF OFFICIAL OBSERVERS

NAME	COMPANY
Adam Shoemaker	ClarkDietrich Building Systems, LLC
Zachary Golden	Intertek B&C
Kurt Golden	Intertek B&C

SECTION 7

TEST PROCEDURE

The sensitivity of the microphones was checked before measurements were conducted.

The transmission loss values were obtained for a single direction of measurement.

Two background noise sound pressure level and five sound absorption measurements were conducted at each of five microphone positions.

Two sound pressure level measurements were made simultaneously in receive and source rooms at each of five microphone positions.

The air temperature and relative humidity conditions were monitored and recorded during all measurements.

Data for flanking limit tests, repeatability measurements, and reference specimen tests are available upon request.

Intertek B&C will store samples of test specimens for four years.

SECTION 8

ACOUSTICAL TEST CALCULATIONS

Transmission loss (TL) at each 1/3 octave frequency is the average source room sound pressure level minus the average receive room sound pressure level, plus, 10 times the log of the specimen area divided by the sound absorption of the receive room with the sample in place.

STC Rating

To obtain the Sound Transmission Class (STC), read the TL of the contour curve at 500 Hz. The sum of the deficiencies below the contour curve must not exceed 32. The maximum deficiency at any one frequency must not exceed 8.

OITC Rating

The Outdoor-Indoor Transmission Class (OITC) is calculated by subtracting the logarithmic summation of the TL values from the logarithmic summation of the A-weighted transportation noise spectrum stated in ASTM E1332.



TEST REPORT FOR CLARKDIETRICH BUILDING SYSTEMS, LLC

Report No.: L3173.05-113-11-R0 Date: 01/05/21

SECTION 9

SPECIMEN DESCRIPTION

SOURCE SIDE GYPSUM BOARD	One Layer 5/8" Type X
STUDS	3-5/8" ProSTUD 20 (18 mil), 20-Gauge Equivalent Steel,
	24" Centers
TRACK	3-5/8" ProTRAK 20 (18 mil), 20-Gauge Equivalent Steel
INSULATION	R-13 Fiberglass Unfaced
STUD TREATMENT	ClarkDietrich Sound Clip (CDSC)
FURRING CHANNELS	25 Gauge (18 mil)
RECEIVE SIDE GYPSUM BOARD	One Layer 5/8" Type X

MATERIAL	ACTUAL DIMENSIONS (inches)	ACTUAL THICKNESS (inches)	MANUFACTURER AND SERIES	QUANTITY	AVERAGE WEIGHT		
SOURCE SIDE	48 by 96	0.625	5/8" USG Sheetrock® Brand Firecode® X Panels (UL Type SCX)	2 sheets	2.20 lbs/ft ²		
BOARD		s sealed with a	" centers on edge and 12" (coustical sealant and foil to	-			
STUD	1-1/4 by 96	3-5/8	ClarkDietrich ProSTUD [®] 20 (18 mil), Steel	5 pieces	0.42 lbs/linear ft		
0.02	Note: Space	ed on 24" cente	ers. Screwed to top and bot	ttom plates.			
INSULATION	24 by 96	3.5	Johns Manville unfaced fiberglass batts	4 pieces	0.21 lbs/ft ²		
INSOLATION	Note: Fiction fit.						
STUD	3 by 1-1/4	0.04	ClarkDietrich Sound Clip™ (CDSC)	15 pieces	0.13 lbs each		
TREATMENT	Note: Use to attach furring channels. Clips spaced on 48" centers.						
FURRING	2-23/32 by 96	0.002	7/8" Steel, 25 gauge (18 mil)	5 pieces	0.24 lbs/linear ft		
CHANNEL	Note: Space	ed on 24" cente	ers perpendicular to studs,	friction fit into	clips.		
RECEIVE SIDE 48 by 96		0.633	5/8" USG Sheetrock® Brand Firecode® X Panels (UL Type SCX)	2 sheets	2.20 lbs/ft ²		
BOARD			2" centers. Perimeter and j e. Screw heads sealed with		ith acoustical		
TOP/ BOTTOM TRACK	1-1/4 by 96	3-5/8	ClarkDietrich ProTRAK® 20 (18 mil), Steel	2 pieces	0.39 lbs/linear ft		



TEST REPORT FOR CLARKDIETRICH BUILDING SYSTEMS, LLC

Report No.: L3173.05-113-11-R0 Date: 01/05/21

TOTAL WEIGHT (lbs)	AVERAGE WEIGHT (lbs/ft ²)
329.63	5.15

Photographs are included in Section 11.

The client did not supply a report drawing of the test specimen.



TEST REPORT FOR CLARKDIETRICH BUILDING SYSTEMS, LLC

Report No.: L3173.05-113-11-R0 Date: 01/05/21

SECTION 10

TEST RESULTS

L3173.01C3 DATA

SPECIMEN AREA	5.95 m²	RECEIVE TEMP.	22.0 °C	SOURCE TEMP	21.7 °C
TECHNICIAN	Zachary Gol	RECEIVE HUMIDITY	45%	SOURCE HUMIDIT	45%

FREQ	BACKGROUND	ABSORPTION	SOURCE	RECEIVE	SPECIMEN	95%	NUMBER
	SPL		SPL	SPL	TL	CONFIDENCE	OF
(Hz)	(dB)	(m²)	(dB)	(dB)	(dB)	LIMIT	DEFICIENCIES
80	37.2	6.6	107	86	21	1.99	-
100	36.8	6.4	107	83	24	2.25	-
125	34.0	6.3	107	78	29	1.29	8
160	40.0	5.5	111	74	38	0.99	2
200	38.9	5.3	110	68	42	0.66	1
250	32.1	5.5	107	62	45	0.68	1
315	25.6	5.9	109	60	49	0.43	0
400	22.1	6.0	110	59	51	0.84	1
500	18.9	6.3	109	55	54	0.33	0
630	20.5	5.9	107	53	54	0.25	0
800	17.7	6.1	107	50	56	0.27	0
1000	16.0	6.4	108	46	62	0.46	0
1250	12.8	7.0	107	42	64	0.47	0
1600	10.0	7.3	105	39	66	0.47	0
2000	9.5	7.9	106	45	59	0.21	0
2500	8.7	9.1	106	45	59	0.34	0
3150	9.8	10.7	104	39	63	0.20	0
4000	10.0	13.4	103	32	67	0.22	0
5000	9.7	17.0	103	27	71	0.29	-
STC RATI	NG	53	(Sound Trai	nsmission Cl	ass)		-
DEFICIEN	CIES	13	(Sum of Dej	ficiencies)			
OITC RAT	ING	37	(Outdoor-Indoor Transmission Class)				

Notes:

1) Receive Room levels less than 5 dB above the Background levels are red.

2) Specimen TL levels listed in red indicate the lower limit of the transmission loss.


3) Specimen TL levels listed in green indicate that there has been a filler wall correction applied



TEST REPORT FOR CLARKDIETRICH BUILDING SYSTEMS, LLC

Report No.: L3173.05-113-11-R0 Date: 01/05/21

L3173.01C3 GRAPH





130 Derry Court York, Pennsylvania 17406

Telephone: 717-764-7700 Facsimile: 717-764-4129 www.intertek.com/building

TEST REPORT FOR CLARKDIETRICH BUILDING SYSTEMS, LLC

Report No.: L3173.05-113-11-R0 Date: 01/05/21

SECTION 11

PHOTOGRAPHS



Photo No. 1 Receive Room View of Installed Specimen



Photo No. 2 Source Room View of Installed Specimen



TEST REPORT FOR CLARKDIETRICH BUILDING SYSTEMS, LLC

Report No.: L3173.05-113-11-R0 Date: 01/05/21

SECTION 12

REVISION LOG

REVISION #	DATE	PAGES	REVISION
0	01/05/21	N/A	Original Report Issue