1512 S BATAVIA AVENUE GENEVA, IL 60134 630-232-0104 An MALION Technical Center

Test Report

RIVERBANK.ALIONSCIENCE.COM FOUNDED 1918 BY WALLACE CLEMENT SABINE

SPONSOR: ClarkDietrich
West Chester, OH

Sound Transmission Loss
RALTM-TL19-092

CONDUCTED: 2019-04-08 Page 1 of 10

ON: Insulated steel stud gypsum board wall, 2 layers on source side, 1 layer on receive side

TEST METHODOLOGY

Riverbank Acoustical LaboratoriesTM is accredited by the U.S. Department of Commerce, National Institute of Standards and Technology (NIST) under the National Voluntary Laboratory Accreditation Program (NVLAP) as an ISO 17025:2005 Laboratory (NVLAP Lab Code: 100227-0) and for this test procedure. The test reported in this document conformed explicitly with ASTM E90-09 (2016): "Standard Test Method for Laboratory Measurement of Airborne Sound Transmission Loss of Building Partitions and Elements." The single number rating of the specimen was calculated according to ASTM E413-16: "Classification for Rating Sound Insulation." A description of the measurement procedure and room specifications is available upon request. The transmission loss values are for a single direction of measurement. The results presented in this report apply to the sample as received from the test sponsor.

SPECIMEN MEASUREMENTS & TEST CONDITIONS

The test specimen was designated by the sponsor as Insulated steel stud gypsum board wall, 2 layers on source side, 1 layer on receive side. The building contractor and RAL staff compiled the following construction specification as follows, in order of installation:

Plates / Base Track

Trade Name: ProTRAK® 20 (18 mil)

Dimensions: 2 @ 2438.4 mm (96 in.) x 31.75 mm (1.25 in.)

Depth: 92.07 mm (3.625 in.)

Steel Thickness: Nominal @ 0.46 mm (0.018 in.)

Measured @ 0.48 mm (0.019 in.)

Installation: Friction fit to test frame over foam sill sealer

Overall Weight: 2.95 kg (6.5 lbs)

Mass per Unit Length: 0.60 kg/m (0.41 lbs/ft)



® RIVERBANK ACOUSTICAL LABORATORIES IS ACCREDITED BY NVLAP (LAB CODE 100227-0) FOR ACOUSTICAL TESTING SERVICES IN ACCORDANCE WITH ISO/IEC 17025:2005 AND FOR THIS PROCEDURE. THIS REPORT MUST NOT BE USED BY THE CLIENT TO CLAIM PRODUCT CERTIFICATION, APPROVAL, OR ENDORSEMENT BY RAL, NVLAP, NIST, OR ANY AGENCY OF THE U.S. GOVERNMENT.

1512 S BATAVIA AVENUE GENEVA, IL 60134 630-232-0104 An MALION Technical Center

Test Report

RIVERBANK.ALIONSCIENCE.COM FOUNDED 1918 BY WALLACE CLEMENT SABINE

Page 2 of 10

ClarkDietrich 2019-04-08

Studs

Trade Name: ProSTUD® 20 (18 mil)

Dimensions: 5 @ 31.75 mm (1.25 in.) x 2743.2 mm (108 in.)

Depth: 92.07 mm (3.625 in.)

Steel Thickness: Nominal @ 0.46 mm (0.018 in.)

Measured @ 0.48 mm (0.019 in.)

Installation: Side studs screwed to test frame, other studs floating in track Fasteners Type W bugle head drywall screws, 31.75 mm (1.25 in.) length

Stud Spacing: 609.6 mm (24 in.) on center

Overall Weight: 8.62 kg (19 lbs)

Mass per Unit Length: 0.63 kg/m (0.42 lbs/ft)

Note: A 6.35 mm (0.25 in.) diameter bead of acoustical sealant was used to seal both sides of the specimen where framing members met the test frame (0.45 kg (1 lbs) total).

Source Side

Layer 1

Material: Type X gypsum board

Dimensions: 1 @ 1219.2 mm (48 in.) x 2743.2 mm (108 in.)

2 @ 609.6 mm (24 in.) x 2743.2 mm (108 in.)

Thickness: 15.88 mm (0.625 in.) Installation: Screwed to studs

Fasteners: Type S bugle head drywall screws, 28.58 mm (1.125 in.) length

Fastener Spacing: 203.2 mm (8 in.) on center at board perimeter

304.8 mm (12 in.) on center at board field

Overall Weight: 72.12 kg (159 lbs)

Mass per Unit Area: 10.78 kg/m² (2.21 lbs/ft²)

Layer 2

Material: Type X gypsum board

Dimensions: 2 @ 1219.2 mm (48 in.) x 2743.2 mm (108 in.)

Thickness: 15.88 mm (0.625 in.)

Installation: Screwed through Layer 1 to studs

Fasteners: Type S bugle head drywall screws, 50.8 mm (2 in.) length

Fastener Spacing: 203.2 mm (8 in.) on center at board perimeter

304.8 mm (12 in.) on center at board field

Overall Weight: 72.8 kg (160.5 lbs)

Mass per Unit Area: 10.88 kg/m² (2.23 lbs/ft²)



® RIVERBANK ACOUSTICAL LABORATORIES IS ACCREDITED BY NVLAP (LAB CODE 100227-0) FOR ACOUSTICAL TESTING SERVICES IN ACCORDANCE WITH ISO/IEC 17025:2005 AND FOR THIS PROCEDURE. THIS REPORT MUST NOT BE USED BY THE CLIENT TO CLAIM PRODUCT CERTIFICATION, APPROVAL, OR ENDORSEMENT BY RAL, NVLAP, NIST, OR ANY AGENCY OF THE U.S. GOVERNMENT.

1512 S BATAVIA AVENUE GENEVA, IL 60134 630-232-0104 An MALION Technical Center

Test Report

RIVERBANK.ALIONSCIENCE.COM FOUNDED 1918 BY WALLACE CLEMENT SABINE

RALTM-TL19-092

Page 3 of 10

ClarkDietrich 2019-04-08

Cavity

Material: R-13 unfaced fiberglass insulation batts

Dimensions: 4 @ 609.6 mm (24 in.) x 2743.2 mm (108 in.)

Thickness: 88.9 mm (3.5 in.)

Installation: Friction fit into cavities between studs

Overall Weight: 8.39 kg (18.5 lbs)

Density: 14.11 kg/m³ (0.88 lbs/ft³)

Receive Side

Material: Type X gypsum board

Dimensions: 2 @ 1219.2 mm (48 in.) x 2743.2 mm (108 in.)

Thickness: 15.88 mm (0.625 in.) Installation: Screwed to studs

Fasteners: Type S bugle head drywall screws, 28.58 mm (1.125 in.) length

Fastener Spacing: 203.2 mm (8 in.) on center at board perimeter

304.8 mm (12 in.) on center at board field

Overall Weight: 72.12 kg (159 lbs)

Mass per Unit Area: 10.78 kg/m² (2.21 lbs/ft²)

Note: Joints and screw heads on the outermost layers of both sides of the partition were sealed with caulk and metal tape (0.23 kg (0.5 lbs) total). Fasteners at the top and bottom tracks were offset to avoid coupling the track to the studs.



1512 S BATAVIA AVENUE GENEVA, IL 60134 630-232-0104 An MALION Technical Center

Test Report

RIVERBANK.ALIONSCIENCE.COM FOUNDED 1918 BY WALLACE CLEMENT SABINE

Page 4 of 10

ClarkDietrich 2019-04-08

Overall Specimen Measurements

Dimensions: 2.44 m (96.0 in) wide by 2.74 m (108.0 in) high

Thickness: 0.14 m (5.5 in)

Weight: 237.68 kg (524 lbs) Transmission Area: 6.689 m² (72 ft²)

Mass per Unit Area: 35.55 kg/m² (7.28 lbs/ft²)

Test Aperture

Size: 2.74 m (9.0 ft.) by 4.27 m (14.0 ft.)

Filler Wall: Yes

Sealed: Entire periphery (both sides) with dense mastic

Test Environment

Source Room

Volume: 177.11 m³

Temperature: $22.8 \, ^{\circ}\text{C} \pm 0.0 \, ^{\circ}\text{C}$ Relative Humidity: $51.0 \, \% \pm 0.0 \, \%$

Receive Room

Volume: 178.33 m³

Temperature: $22.8 \,^{\circ}\text{C} \pm 0.0 \,^{\circ}\text{C}$ Relative Humidity: $50.0 \,\% \pm 0.0 \,\%$

Requirements

Temperature: 22° C +/- 2° C, not more than 3° C change over all tests.

Relative Humidity: $\geq 30\%$, not more than +/- 3% change over all tests.



1512 S BATAVIA AVENUE GENEVA, IL 60134 630-232-0104 An MALION Technical Center

Test Report

RIVERBANK.ALIONSCIENCE.COM FOUNDED 1918 BY WALLACE CLEMENT SABINE

RALTM-TL19-092

Page 5 of 10

ClarkDietrich 2019-04-08



Figure 1 – Specimen mounted in test opening, as viewed from receive room



Figure 2 – Framing members installed in test aperture



® RIVERBANK ACOUSTICAL LABORATORIES IS ACCREDITED BY NVLAP (LAB CODE 100227-0) FOR ACOUSTICAL TESTING SERVICES IN ACCORDANCE WITH ISO/IEC 17025:2005 AND FOR THIS PROCEDURE. THIS REPORT MUST NOT BE USED BY THE CLIENT TO CLAIM PRODUCT CERTIFICATION, APPROVAL, OR ENDORSEMENT BY RAL, NVLAP, NIST, OR ANY AGENCY OF THE U.S. GOVERNMENT.

1512 S BATAVIA AVENUE GENEVA, IL 60134 630-232-0104

Test Report

An MALION Technical Center

RIVERBANK.ALIONSCIENCE.COM FOUNDED 1918 BY WALLACE CLEMENT SABINE

Page 6 of 10

ClarkDietrich 2019-04-08



Figure 3 – Typical sealing of perimeter framing members, detail of floating stud



Figure 4 – Stud cavity insulation partially installed



® RIVERBANK ACOUSTICAL LABORATORIES IS ACCREDITED BY NVLAP (LAB CODE 100227-0) FOR ACOUSTICAL TESTING SERVICES IN ACCORDANCE WITH ISO/IEC 17025:2005 AND FOR THIS PROCEDURE. THIS REPORT MUST NOT BE USED BY THE CLIENT TO CLAIM PRODUCT CERTIFICATION, APPROVAL, OR ENDORSEMENT BY RAL, NVLAP, NIST, OR ANY AGENCY OF THE U.S. GOVERNMENT.

1512 S BATAVIA AVENUE GENEVA, IL 60134 630-232-0104 An MALION Technical Center

Test Report

RIVERBANK.ALIONSCIENCE.COM FOUNDED 1918 BY WALLACE CLEMENT SABINE

> RALTM-TL19-092 Page 7 of 10

ClarkDietrich 2019-04-08

TEST RESULTS

Sound transmission loss values are tabulated at the eighteen standard frequencies. A graphic presentation of the data and additional information appear on the following pages. The precision of the transmission loss test data is within the limits set by the ASTM Standard E90-09 (2016).

FREQ.	<u>TL</u>	ΔTL	<u>DEF.</u>	FREQ.	TL	ΔTL	DEF.
100	19	0.65	0	800	56	0.18	0
125	33	0.92	2	1000	57	0.10	0
160	37	0.69	1	1250	58	0.11	0
200	41	0.48	0	1600	54	0.18	1
250	44	0.36	0	2000	47	0.13	8
315	46	0.45	1	2500	49	0.09	6
400	49	0.25	1	3150	54	0.08	1
500	53	0.21	0	4000	58	0.09	0
630	55	0.19	0	5000	61	0.08	0

STC=51

ABBREVIATION INDEX

FREQ. = FREQUENCY, HERTZ

TL = TRANSMISSION LOSS, dB

 $\Delta TL = 95\%$ CONFIDENCE INTERVAL FOR TL MEAUREMENTS, dB

DEF. = DEFICIENCIES, dB BELOW STC CONTOUR (SUM OF DEF = 21)

STC = SOUND TRANSMISSION CLASS

Tested by_

Marc Sciaky

Senior Experimentalist

Report by_

Malcolm Kelly

Acoustical Test Engineer

Approved by

Eric P. Wolfram

Laboratory Manager



® RIVERBANK ACOUSTICAL LABORATORIES IS ACCREDITED BY NVLAP (LAB CODE 100227-0) FOR ACOUSTICAL TESTING SERVICES IN ACCORDANCE WITH ISO/IEC 17025:2005 AND FOR THIS PROCEDURE. THIS REPORT MUST NOT BE USED BY THE CLIENT TO CLAIM PRODUCT CERTIFICATION, APPROVAL, OR ENDORSEMENT BY RAL, NVLAP, NIST, OR ANY AGENCY OF THE U.S. GOVERNMENT.

1512 S BATAVIA AVENUE GENEVA, IL 60134 630-232-0104 An MALION Technical Center

RIVERBANK.ALIONSCIENCE.COM FOUNDED 1918 BY WALLACE CLEMENT SABINE


Test Report

RALTM-TL19-092
Page 8 of 10

ClarkDietrich 2019-04-08

SOUND TRANSMISSION REPORT

Insulated steel stud gypsum board wall, 2 layers on source side, I layer on receive side



STC=51

TRANSMISSION LOSS
SOUND TRANSMISSION CLASS CONTOUR



® RIVERBANK ACOUSTICAL LABORATORIES IS ACCREDITED BY NVLAP (LAB CODE 100227-0) FOR ACOUSTICAL TESTING SERVICES IN ACCORDANCE WITH ISO/IEC 17025:2005 AND FOR THIS PROCEDURE. THIS REPORT MUST NOT BE USED BY THE CLIENT TO CLAIM PRODUCT CERTIFICATION, APPROVAL, OR ENDORSEMENT BY RAL, NVLAP, NIST, OR ANY AGENCY OF THE U.S. GOVERNMENT.

1512 S BATAVIA AVENUE GENEVA, IL 60134 630-232-0104

Test Report

An MALION Technical Center

RIVERBANK.ALIONSCIENCE.COM FOUNDED 1918 BY WALLACE CLEMENT SABINE

> RALTM-TL19-092 Page 9 of 10

ClarkDietrich 2019-04-08

APPENDIX A: Extended Frequency Range Data

Specimen: Insulated steel stud gypsum board wall, 2 layers on source side, 1 layer on receive side (See Full Report)

The following non-accredited data were obtained in accordance with ASTM E90-09 (2016), but extend beyond the defined frequency range of 100Hz to 5,000Hz. These unofficial results are representative of the RAL test environment only and intended for research & comparison purposes. Sampling precision observed during this procedure is reported below.

1/3 Octave Band	Sound	
Center Frequency	Transmission Loss	ΔTL (Eq. A2.5)
(Hz)	(dB)	(dB)
31.5	19	1.65
40	20	0.86
50	18	0.96
63	16	0.51
80	15	0.56
100	19	0.65
125	33	0.92
160	37	0.69
200	41	0.48
250	44	0.36
315	46	0.45
400	49	0.25
500	53	0.21
630	55	0.19
800	56	0.18
1000	57	0.10
1250	58	0.11
1600	54	0.18
2000	47	0.13
2500	49	0.09
3150	54	0.08
4000	58	0.09
5000	61	0.08
6300	62	0.10
8000	62	0.13
10000	59	0.11
12500	54	0.15



® RIVERBANK ACOUSTICAL LABORATORIES IS ACCREDITED BY NVLAP (LAB CODE 100227-0) FOR ACOUSTICAL TESTING SERVICES IN ACCORDANCE WITH ISO/IEC 17025:2005 AND FOR THIS PROCEDURE. THIS REPORT MUST NOT BE USED BY THE CLIENT TO CLAIM PRODUCT CERTIFICATION, APPROVAL, OR ENDORSEMENT BY RAL, NVLAP, NIST, OR ANY AGENCY OF THE U.S. GOVERNMENT.

1512 S BATAVIA AVENUE GENEVA, IL 60134 630-232-0104

An MALION Technical Center

RIVERBANK.ALIONSCIENCE.COM FOUNDED 1918 BY WALLACE CLEMENT SABINE

Test Report

RALTM-TL19-092 Page 10 of 10

ClarkDietrich 2019-04-08

APPENDIX B: Instruments of Traceability

Specimen: Insulated steel stud gypsum board wall, 2 layers on source side, 1 layer on receive side (See Full Report)

		Serial	Date of	Calibration
Description	Model	Number	Certification	Due
System 2	Type 3160-A-042	3160- 106974	2018-08-09	2019-08-09
Bruel & Kjaer Mic And Preamp D	Type 4943-B-001	2311440	2018-09-28	2019-09-28
Bruel & Kjaer Pistonphone	Type 4228	2781248	2018-08-06	2019-08-06
EXTECH Hygro 330	SD700	A083330	2018-09-07	2019-09-07
EXTECH Hygro 322	SD700	A083322	2018-09-07	2019-09-07

APPENDIX C: Revisions to Original Test Report

Specimen: Insulated steel stud gypsum board wall, 2 layers on source side, 1 layer on receive side (See Full Report)

Date Revision

Original report issued 2019-04-24



